
## **CORNER RECORD**

 Agency Index
 CR24-026

 Document Number
 028-063-06 (b)

City of MILL VALLE	Υ	County of MARIN , Califo			
Brief Legal Description	on 1/2" REBAR, BRO	1/2" REBAR, BROKEN CAP, ILLEGIBLE, AS SHOWN ON CORNER RECORD APN 028-063-0			
	CORNER TYPE  Government Corner Control Meander Property Rancho Other		COORDINATES (OPTIONAL)  N E Elevation Units		
	Date of Survey	03/05/2024	Vertical Datum Complies with Public	Resources Code §§8801-8819 Resources Code §§8890-8902	
PLS Act Ref.:	8765(d)	<b>X</b> 8771	8773	Other:	
Corner/ Monument:	Left as found  Found and tagged	Established Reestablished	Rebuilt  Referenced	Pre-Construction Post-Construction	
SET IN THE CORI	RECT LOCATION BY T SURVEYOR'S S		EYOR OR ENGINEER.		
This Corner Record was	prepared by me or under	my direction in conforma	ance with	SET LAND SUP	
the Professional Land Signed	COUNTY SURVEYO	May 15, 2024  P.L.S. or <del>R.C.E. No.</del> PR'S STATEMENT	6637	No. 6637	
This Corner Record was	received May 15, 20	024			
and examined and filed Signed Title County Surv County Surveyor's Cor	-	P.L.S. No.	8176	STATE OF CALIFORNIA	



- FOUND 1/2" REBAR, BROKEN PLASTIC CAP, ILLEGIBLE, AS SHOWN ON CORNER RECORD APN 028-063-06.
- SET 3/4" IRON PIPE WITH 3/4" BRASS TAG, STAMPED "RP LS 6637".