## **CORNER RECORD**

Document Number 38 - 122-21

City of <u>11buron</u>	_	ounty of _	Ma	<u>ırın</u>	, California
Brief Legal Description: <u>Cer</u>	nterlines of Marti	nique Av	enue, Ant	illes Wo	y, and Jamaica Street, City of Tiburon
CORNER TYPE	CO	ORDINA	TES (Opti	ional)	
	Government Corner		Control		N
h	Meander		Property		Zone NAD27
	Rancho		Other		Vert. Datum: NGVD29 □ NAVD88 □
-	Date of Survey S	eptember	26, 2013		Meas. Units: Metric □ Imperial □
Corner - Left as found	] Found and tag	ged 🗌	Established	j 🗆	Reestablished Rebuilt 🗆
In the course of resurfacenterline monuments  I was able to establish  monuments on Martin	acing the streets in a congress of the congres	n this ar eplace the clong Ma ally on linue ue on Ar	rea, the pone the monum rtinique, in the and the ntilles was	aving contents as between e overa	ed to establish or reestablish the corner:  ontractor removed five (5) existing  s close as possible to their original position.  n Antilles and St. Thomas. All remaining  ll distance fit the map distance within  ed using the direction between the existing
	•				set: <u>All monuments as described above had</u> replaced with a 2" brass disk, stamped PLS
4760, in a well monur	nent.				
This Corner Record was pre the Land Surveyor's Act on Signed Ralph H.		my direction	013 .E. No. <u>PL</u>		—· ( No.4760 )
This Corner Record was rec			_	3	OF CALIFO
and examined and filed NO Signed Signed Co.  Title DEPUTY CO.  County Surveyor's Comme	P.L.	2012 s. or r.c	E. No		A SIMONITCH AND SUPPLIED G. BENDONITCH AND STATE OF CALIFORNIA TO THE CALIFORNIA TO

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: monument to the north and the existing monument at Antilles and Martinique. Even though the record angle did not fit the map angle, I held the direction between monuments, and set the location of the monument to the south at 39.52 feet. At Martinique and Trinidad, the westerly of the two monuments was missing. The distance between the two remaining monuments at Antilles and Trinidad (north) was measured to be 125.07'. The record dimension is 125'. I set the position at Martinique and Trinidad (south) at a distance of 120.00' from the monument at Antilles. This position of the new monument fit the record angle between Martinique and the existing monument on Trinidad (south). The new position at Martinique and Jamaica was set using the record dimension from the existing monument at Antilles and Martinique of 475.00 feet. The new monument at Saba Lane and Jamaica was set using the direction established by the newly set point at Jamaica and Martinique and the existing monument south of Saba on Jamaica. The record distance of 44.20 feet was used to establish the position. Heading south on Jamaica the EC monument was set using the closure between the two existing monuments. The distance and angle fit with the record dimensions and the new position was set at the map location.



ENGINEERS / SURVEYORS / PLANNERS

325 TESCONI CIRCLE SANTA ROSA, CA 95401 PH: 707-583-8500 FAX: 707-583-8539 Subject RE-SET MISSING MONUMENTS
ANTILLES WAY, MARTINIQUE AVE, TIBURON
Job No. 20139111-50
By CAG Date 10/03/13 Chkd.RHT
SHEET 3 OF 4

MARTINIQUE AVE
475.00 (M&R1)

--- N70°50°00"E 1125.06 ---(N70°50'00"E 1125.00-R1) JAMAICA

ST

353.29 (353.24-CALC R1&R2)

296.77 (M&R2)