


CORNER RECORD

Document Number 143-451-07City of VICINITY OF NOVATOCounty of MARIN, CaliforniaBrief Legal Description Control Monument of 8 O.S. 22, 17 R.M. 53 ON 'H' LANE

CORNER TYPE

Government Corner ☐ Control ☒
Meander ☐ Property ☐
Rancho ☐ Other ☐
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND RR SPIKE 1210' +/- SE'LY OF BAYIA DR / 'H' LANE
INTERSECTION IN NOVATO. SET Reference points
prior To paving of 'H' Lane - To reset later
as Standard Monument

A description of the physical condition of the monument as found and as set or reset:

RR Spike on Surface - Susceptible to destruction
via paving job.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Feb 20 2013

Signed Michael G. Brogan P.L.S or R.C.E. No. LS 5767



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 20, 2013
and examined and filed MARCH 28, 2013

Signed Richard G. Simonitch P.L.S or R.C.E. No. 7821

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

NOT TO SCALE

FOUND

CL MONUMENT AT BAHIA DR.
SEE 17 R.M. 53, 8 O.S. 22,
AND 14 R.M. 3


APN143-451-07
LOT 289 17 R.M. 53

SET
MAG NAIL D/W CURB
NO. 160

S 43 35' 15" E
CENTERLINE BASIS OF BEARING
PER 8 O.S. 22 / S43 35' 40"E
PER 17 R.M. 53 AND 14 R.M. 3

SET
PAINT MARK
EDGE OF D/W
NO. 151

SET
HUB AND TACK
OFF PAVEMENT



H LANE 60' WIDE

N18° 06' 01"E
24.62 TIE

FOUND
RR SPIKE 0.15'
SW'LY OF CENTERLINE

N34° 02' 51"E
17.23
TIE

SET
TACK IN RUNNER BOARD
D/W OF NO. 145