


CORNER RECORD

Document Number 143-451-076
City of Vicinity of Novato County of MARIN, California

Brief Legal Description Control monument on 'H' Lane, 80522, 17 R.M. 53



CORNER TYPE

Government Corner ☐ Control ☒
Meander ☐ Property ☐
Rancho ☐ Other ☐
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☒

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See corner record 143-451-07 filed March 28, 2013
for reference points set

A description of the physical condition of the monument as found and as set or reset:


RR Spike on 'H' Lane, (See Back) rebuilt as a
Standard County Monument: punched brass disc in
concrete, stamped "MARIN County Surveyor"

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on December 6 2013

Signed Michael B. Brogan P.L.S. or R.C.E. No. 455767



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 6, 2013

and examined and filed JANUARY 16, 2014

Signed Richard G. Simonitch P.L.S. or R.C.E. No. 7821

Title DEPUTY CO. SURVEYOR



County Surveyor's Comment _____

NOT TO SCALE

FOUND

CL MONUMENT AT BAHIA DR.
SEE 17 R.M. 53, 8 O.S. 22,
AND 14 R.M. 3

APN143-451-07
LOT 289 17 R.M. 53

SET
MAG NAIL D/W CURB
NO. 160

S 43° 35' 15" E
CENTERLINE BASIS OF BEARING
PER 8 O.S. 22 / S43° 35' 40" E
PER 17 R.M. 53 AND 14 R.M. 3

Dec 2013
REBUILT RR spike

SET
PAINT MARK
EDGE OF D/W
NO. 151

SET
HUB AND TACK
OFF PAVEMENT


N18° 06' 01" E
24.62 TIE

FOUND
RR SPIKE 0.15'
SWLY OF CENTERLINE

SET
TACK IN RUNNER BOARD
D/W OF NO. 145

N34° 02' 51" E
17.23
TIE

H LANE 60' WIDE



SURVEY SECTION
MARIN COUNTY
PUBLIC WORKS