


CORNER RECORD

Document Number 93-98553City of Vicinity of San Anselmo County of Marin, CaliforniaBrief Legal Description Lot 412; Map of Sleepy Hollow Unit Four, 6-Maps-79

CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey 11 April 1995

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Set 3/4" I.D. galvanized iron pipe, with plastic plug "L.S. 4794" at the northeasterly and northwesterly corners of Lot 412, Map of Sleepy Hollow Unit Four, recorded in Book 6 of Maps, at Page 79, Marin County Records.

A description of the physical condition of the monument as found and as set or reset: as shown on reverse side.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on 11 April 1995.


Signed [Signature] L.S. or R.C.E. Number L.S. 4794



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 18 April 1995 and examined and filed 19 April 1995.


Signed [Signature] Title DCS



County Surveyor's Comment _____

Philip A. Dankin & Associates
Survey No. 354
176-104-02

with compass disc stamped 3230



LANDS OF HAROLD & JOSEPH LANG


Set 3/4" 3.0. gable iron pipe
with plastic plug & 1/2" 4294"

Scale 1" = 100'

North

with compass disc stamped 3230

CORNER RECORD

Document Number 93-98553City of Vicinity San AnselmoCounty of Marin, CaliforniaBrief Legal Description Lot 412; Map of Sleepy Hollow Unit 4; 6-Maps-79

CORNER TYPE

Government Corner ☐Control ☐Meander ☐Property ☒Rancho ☐Other ☐Date of Survey 25 April 1996COORDINATES
(Optional)

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

 Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Set 3/4" I.D. galvanized iron pipe, with plastic plug "LS 4794" at the
southwesterly and southeasterly corners of Lot 412; Map of Sleepy
Hollow Unit Four, recorded in Book 6 of Maps, at Page 79,
Marin County Records

 A description of the physical condition of the monument as found and as set or reset: as shown on
reverse side.


SURVEYOR'S STATEMENT

 This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on 25 April 1996.

 Signed [Signature] L.S. or R.C.E. Number LS 4794


COUNTY SURVEYOR'S STATEMENT

 This Corner Record was received MAY 20 1996 and examined
 and filed MAY 21 1996.


 Signed [Signature] Title Deputy


County Surveyor's Comment _____

Approx.
North

Scale 1"=100'

Set 3/4" I.D. galv. iron pipe with plastic
plug "LS 4794"



Phillip A. Danskin & Associates

Survey No 354

APN 176-101-02