

CORNER RECORD


A.P.N. 176-101-04

Document Number 93-034099

City of Vicinity of San Anselmo

County of Marin, California

Brief Legal Description Lot 410, Map of Sleepy Hollow Unit Four, 6-Maps-79



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey 2 May 1995

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Set 3/4" G.D. galvanized iron pipe with plastic plug "L.S. 4794" at the north-
westerly, northeasterly, ~~southeasterly~~ and southwesterly corners of Lot 410, Map
of Sleepy Hollow Unit Four, recorded in Book 6 of Maps, at Page 79,
Marin County Records.

A description of the physical condition of the monument as found and as set or reset: as shown on
reverse side.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on 2 May 1995.

Signed PI DL L.S. or ~~REDACTED~~ Number L.S. 4794

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received May 4 1995 and examined

and filed May 5 1995.


Signed John M. Wooley Title Deputy

County Surveyor's Comment _____





APPROX.
NORTH



Phillip A. Danskin & Associates
Land Surveyor
Sonoma, Ca.

Survey No 357

CORNER RECORD


A.P.N. 176-101-04

Document Number 23-034099

City of Vicinity of San Anselmo

County of Marin, California

Brief Legal Description Lot 410, Map of Sleepy Hollow Unit Four, 6-Maps-79



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey 2 May 1995

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

found original hub with galvanized nail at the south-easterly corner of Lot 410, Map of Sleepy Hollow Unit Four, recorded in Book 6 of Maps, at Page 79, Marin County Records.

A description of the physical condition of the monument as found and as set or reset: as shown on reverse side

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 2 May 1995.

Signed [Signature] L.S. or ~~NUM.~~ Number L.S. 4794

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received May 4 1995 and examined and filed May 5 1995.

Signed [Signature] Title Deputy

County Surveyor's Comment _____



Shulick, A. Damskin & Associates



APPROX. NORTH