


# CORNER RECORD

Agency Index CR24-024Document Number 200-252-26City of UNINCORPORATED MILL VALLEY County of MARIN, CaliforniaBrief Legal Description: LOT 49 OF "PARCEL MAP OF REVISED BOUNDARIES LOTS 49-53, MAP OF MARINVIEW UNIT 1",  
RECORDED 8/20/1970 IN BOOK 5, PAGE 25, MARIN COUNTY RECORDS.**CORNER TYPE****COORDINATES (Optional)**Government Corner  Control   
Meander  Property   
Rancho  Other Date of Survey 10/10/2016

N: \_\_\_\_\_ E: \_\_\_\_\_

Elevation: \_\_\_\_\_

Units: Metric  US Survey Foot 

Horizontal Datum \_\_\_\_\_

Zone: \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum: \_\_\_\_\_

 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902PLS Act Ref.:  8765(d)  8771  8773  Other:Corner/  
Monument:  Left as found  Established  Rebuilt  Pre-Construction  
 Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

 See sheet #2 for description(s):FOUND (2) 2.5" BRASS DISK & PUNCH STAMPED "RCE 8181" IN HANDHOLE ALONG THE CENTERLINE OF CARERRA DRIVE;  
FOUND 2"X2" WOOD HUB & TACK AT THE MOST WESTERLY CORNER OF LOT 50;  
SET 5/8" REBAR & PLASTIC CAP STAMPED "LS 8708" AT THE MOST EASTERLY CORNER LOT 49 (AT THE R/W LINE);  
SET 5/8" REBAR & PLASTIC CAP STAMPED "LS 8708" AT THE ANGLE POINT BETWEEN LOTS 49 & 50;  
SET 5/8" REBAR & PLASTIC CAP STAMPED "LS 8708" ALONG THE SOUTHEASTERLY LINE OF LOT 49;  
AS SHOWN ON PAGE 2.**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on OCTOBER 10, 2016Signed: Seren L Goodwin P.L.S.No. 8708**COUNTY SURVEYOR'S STATEMENT**The Corner Record was received March 15, 2024and examined and filed March 28, 2024Signed: T.W. Park P.L.S. No. 8176Title: County Surveyor**County Surveyor's Comment**

