CORNER RECORD	Document Number APN 200-302-22
City of TIBURON	
Brief Legal Description LOT 185, 15 RM	140 APN 200-305-22
CORNER TYPE  Government Corner Contr  Meander Proper Rancho Contr  Date of Survey 7-25-06	Zone NAD27 □ NAD83 □  NAD83 Epoch  Elev  Vot Det m: NOVD30 □ NAVD88 □
Corner – Left as found □ Found and tagged □ E	Established 🗆 Reestablished 🖄 Rebuilt 🗆
Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  EXISTING CORNERS NOT FOUND. RE-ESTABLISHED  LOT CORNERS FROM RECORD BEARINGS > DISTANCES  SHOWN ON 15 RM 40.  BASIS OF BEARINGS: DURANT WAY, FOUND BRASS  DISK IN WELL MONUMENTS  A description of the physical condition of the monument as found and as set or reset:  SET 1/3" IRON PIPE WITH PLASTIC PLUG  STAMPED LS 7037 AT FRONT > REAR LOT CORNERS.	
SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in the Land Surveyor's Act on      July 25   0   0   0   0   0   0   0   0   0	2006 Exp. 12-31-06
Signed Michael Z. Ford P.L.S or R.C.E. No. L	5 723 TEGFCALFOR
COUNTY SURVEYOR'S STATEMENT	SD LAND SUA
This Corner Record was received <u>AUGUST</u> 7, 200 and examined and filed <u>SEPTEMBER</u> 28, 2006 Signed P.L.S OF R.C.E. No	G SEAL CO SEAL
County Surveyor's Comment	

