


A. P. #45-053-24

CORNER RECORDCOUNTY OF MARIN T. _____ R. _____ MERIDIAN _____ CALIFORNIACORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐CORNER IDENTIFICATION — DATE OF VISIT OCT. 30, 1987

BEING THE SOUTHEAST CORNER OF PARCEL 'A' AS SHOWN ON PARCEL
MAP "LAND DIVISION OF LOTS 22 THRU 25 AND 34 THRU 37 PIPE
LINE TRACT 4-M-45 MARIN COUNTY - CALIFORNIA", FILED FOR
RECORD JULY 12, 1967 IN BOOK 2 MAPS, AT PAGE 2, MARIN COUNTY
RECORDS.

CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

ORIGINAL SET 1" O.D. X 18" IRON PIPE AND TAG L.S. 3226 WAS
DESTROYED BY GRADING OF DRIVEWAY.

AP#45-053-24

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET $\frac{1}{2}$ " x 18" IRON PIPE WITH PLASTIC PLUG STAMPED L.S. 4419

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

JOB #M87-156

1

