

A.P. #55-171-13

CORNER RECORD

COUNTY OF MARIN

T. _____

R. _____


MERIDIAN _____

CALIFORNIA

CORNER TYPE: GOV'T. CORNER ☐MEANDER ☐RANCHO ☐CONTROL ☐OTHER ☒

CORNER IDENTIFICATION — DATE OF VISIT _____

19____

CORNER — LEFT AS FOUND ☐FOUND AND TAGGED ☐REESTABLISHED OBLITERATED CORNER ☒REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND MONUMENTATION PER 29 OS 83

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 3/4" IRON PIPE TAGGED P.L.S. 5296

AP N^o 55-171-13CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐SECOND ☐THIRD ☐STATIONS USED: NGS (USC & OS) ☐STATE ☐COUNTY ☐OTHER ☐

STATION _____

STATION _____

ZONE _____

ELEVATION _____

NORTHINGS (Y) _____

EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

LANDS OF LOMAS

29 OS 83

FND 3/4" I.P.
P.L.S. 5296S 81°00'W
143.20

HAKANSON

0.92
0.07
FND HUB RCE 11181
S 14°58'17"E
33.630.21
0.29
OLD HUB
KENNEY
S 57°30'E 35.000.65
0.70
FND HUB RCE 11181
S 70°30'E 35.00

N 56°34'E 102.87

FND 3/8" REBAR

SET 3/4" I.P.
P.L.S. 5296 166.90(TOTAL)
N 33°26'W 43.99
(151.22)LOOK
S 56°34'W
6 RM 67

TIBURON

R = 530



(CA. HWY RTE 52)

FND 3/4" I.P.
P.L.S. 5296

BLVD.

1" = 50'

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON JANUARY 10SIGNED: [Signature]L.S. or R.C.E. No. P.L.S. 5296

COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED Jan. 21 1992
AND EXAMINED AND FOUND Jan. 23 1992No. 004083Exp. 3/31/92Title: Dep. Co. SurveyorDOCUMENT 6411

STATE (PRINT ON BACK OF SHEET)

YES ☐NO ☒