CORNER RECORD	Document I	Number <u>078-6</u>	32-18
City of Mill Valley	County of	Marin	, California
Brief Legal Description 5/14 line of Lot Z	61,2 R.M. 55		
CORN	IER TYPE	COORDINATES	6 (Optional)
	☐ Control ☐ ☐ Property ☒	NEZoneNAI	D27 🗆 NAD83 🗆
Rancho Date of Survey 1/3	□ Other □ 30/07	Vert. Datum: NGVD29 Meas. Units: Metric	□ NAVD88 □ □ □ Imperial □
Corner – Left as found ☐ Found and tag	ged Established	Reestablished	Rebuilt 🛚
Identification and type of corner found: Evidence used to See page Z of Z	o identify or procedure used		
ì			
		-	
A description of the physical condition of the monument See Page 2 of 2	as found and as set or res	et:	
See Page 201 2			
CUDVEVOD/C CTATEMEN	NIT	(60)	AL LAND
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my		with Williams	THE SEPTEMBER
n , –	y direction in conformance ZØØ7	Willi	OR Strain or
to an			Exp. 09/30/08
Signed P.L.S or R.O	C.E. No. <u>6784</u>		OF CALIFORNIA
COUNTY SURVEYOR'S STAT	EMENT		The second secon
This Corner Record was receivedFEBRUARY_14	4, 2007	A. C.	CO LAND SCA
and examined and filed MARCH 26, 2007			GTACA O
	C.E. No. 7128		8
Title COUNTY SURVEYOR	0.E . No	70	Exp. <u>12-31-08</u> No. 7128
County Surveyor's Comment			NO. 7128

