CORNER RECOR	D			Docum	nent Numl	oer <u>A.P.</u> #	028-081-	02
City of MILL VALLE	EY			County	of	MARIN	, Ca	alifornia
Brief Legal Description	NORTHWESTERLY 1/2 OF SUBDIVISION 6 OF LOT 18, 3 R.M. 82							
	CORNER TYPE		COORDI	NATES (Option		V.		
	Government Corner		Control]	E	NAD27	NAD83
	Meander		Property	\boxtimes	Elev.		ch	
	Rancho		Other			. Datum: Units:	NGVD29 □ Metric□	NAVD88 Imperial
<u> </u>	Date of Survey							
Comer- Left as found	Found and tagged	d 🔲	Established	⊠ Ree	stablished	☐ Rebu	ilt 🔲	
Identification and type of o	corner found: Evidence	used to	identify or pro	ocedure use	d to estab	lish or reestab	lish the corner:	
Identification and type of c	TERLY 1/2 OF SUBDIVIS	SION 6	LOT 18, 3 R USING STREET	MONUMEN	TS ON TH	ROCKMORTON	AVENUE PER	3 R.M. 82
AND AS SHOWN ON 27	0.S. 42.							

A description of the physic	eal condition of the mon	ument a	as found and as	s set or rese	:t: _			
		SEE	SHEET 2.					
			····			<u> </u>		
					·····			
SUR	VEYOR'S STATEMENT							
This Corner Record was pr		my dire	ection in confor	mance with				ANI
<u>.</u>	,	•						SED LAND SUPL
the Land Surveyor's Act or				2006			//	Signal of the second of the se
Signed Kawbree F	Doyle	P.L.S.	or R.C.E. No.	<u>P.L.</u>	S. 4694			No. 4694 Exp. 9/30/07
COUNTY	SURVEYOR'S STATEMENT						\	OF CALLEGENTY
This Corner Record was re		GUS	ST 16,	2006				OF CALIFO
This corner record was re			•					TAND
and examined and filed	SEPTEN	1BE	R 14,	2006			!	TACA
Signed		P.L.S. o	or R.C.E. No.	712	8			SEAL RY
Title COUNTY SU	RVERIOD							Exp. 12-31-06
								No. 7128
County Surveyor's Comment								O-CALIFY
					-			

