CORNER RECORD				Document Number APN 028-132-08						
City of Mill Valley										
Brief Legal Description Lots 18	and 19	per	2	Map	S	129				
		ER TYPE				COOR	DINATES	(Ontional)		
1 ' 1	ent Corner	□ Co	ntrol		E		:	27 🗆 NAD8:		
Meander			operty		NAL	083 Epoch		27 LI NAD8:	B 🗆	
Rancho Date of S	Survey		her	<u> </u>	Vert	 . Datum: as. Units:	NGVD29	J NAVD88 J Imperial		
Corner - Left as found □ F	ound and tage	ged 🛚	Estab	lished 🏻	l	Reestab	olished 🗆	Rebuilt	П	
Identification and type of corner found: Ev	idence used to	identify o	or proce	edure use	d to	establish	or reestab	lish the corn	er:	
See page 2 of 2					-					
					•					
				-						
		•								
A description of the physical condition of t See Page 2 of Z										

-										
SURVEYOR	N'S STATEMEN	NT						AL LAND S LEY T. GR		
This Corner Record was prepared by m	e or under my	direction	in cor	oformance	with	า	500	· · · · · · · · · · · · · · · · · · ·	<u> </u>	
the Land Surveyor's Act on	70105						1		<i>[</i>]∡[
Signed Signed	P.L.S or R.0	CE No	670	34			13:	Exp. 09/30/08 PLS 678A		
eigned State of the state of th	1.L.O 01 N.C	J.L. NO		<u> </u>	-		SIE	OF CALIFO	>	
COUNTY SURVE	EYOR'S STATI	EMENT						Asher San		
This Corner Record was received:	4-07							DLAND,	8/	
and examined and filedDECEME		2007	,					TACK	STORY OF	
Signed	P.L.S o r R. (712 \$)		_	. E	ප්	^퉷임	
Title COUNTY SURVEYOR	;				***************************************	 .		Exp. <u>12-31</u> No. 7128	-08/*/	
								CF CAL		
County Surveyor's Comment	:	-			**************************************	·		aggism) of		

