CORNER RECORD Agency Index CR24-036 Document Number 028-181-12(a) City of MILL VALLEY County of MARIN . California Brief Legal Description FOUND 3/4" IRON PIPE WITH CAP "DANSKIN PLS 4794" AS SHOWN ON 2017 MAPS 94, MARIN COUNTY RECORDS. **COORDINATES** (OPTIONAL) **CORNER TYPE** N. Government Corner Control Elevation U.S. Survey Foot Meander Property Units Metric Rancho Other **Horizontal Datum** Epoch Date 03/05/2024 Date of Survey Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) 8771 8773 Other: Pre-Construction Left as found Established Rebuilt Corner/ Monument: Found and tagged Post-Construction Reestablished Referenced Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): SEE REFERENCE POINTS ON PAGE 2, USED FOR PERPETUATION THROUGH CONSTRUCTION. NOTE: NO WARRANTY IS EXPRESSED OR IMPLIED THAT THE MONUMENTS SHOWN HEREON HAVE BEEN SET IN THE CORRECT LOCATION BY THE ORIGINAL SURVEYOR OR ENGINEER.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on May 15, 2024

Signed P.L.S. or R.C.E. No. 6637

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received May 15, 2024

and examined and filed May 22, 2024

Signed P.L.S. No. 8176

Title County Surveyor

County Surveyor's Comment



LEGEND

- FOUND 3/4" IRON PIPE WITH PLASTIC CAP "DANSKIN PLS 4794" AS SHOWN ON 2017 MAPS 94.
- \square SET MAG NAIL IN CONCRETE WITH 3/4" BRASS TAG, STAMPED "RP LS 6637".
- O SET 3/4" IRON PIPE WITH 3/4" BRASS TAG, STAMPED "RP LS 6637".