


CORNER RECORD

Document Number 029-091-11City of Mill ValleyCounty of Marin, CaliforniaBrief Legal Description Lands of DeBartolo, Record of Survey, 2014 RS 37

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found monuments as shown on Plat.


A description of the physical condition of the monument as found and as set or reset:

Set monuments as shown on Plat.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on November 18, 2014

Signed Charles D. Allen ~~P.L.S.~~ or R.C.E. No. 21998



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 19, 2014

and examined and filed MARCH 12, 2015

Signed Richard G. Simonitch P.L.S. or R.C.E. No. 7821

Title DEPUTY



County Surveyor's Comment _____

