


CORNER RECORD

Document Number APN 029-114-13City of MILL VALLEYCounty of MARIN, CaliforniaBrief Legal Description A PORTION OF LOT 16, 1 RM 85 & A PORTION OF LOT 77, 3 RM 51
2000 OS 156

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey APRIL 13, 2001

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FND. NAIL & TAG, PLS 5296 AND FND. 3/4" I.P. TAGGED PLS 5296
AS SHOWN ON BOOK 2000 MAPS PAGE 156 AND ON REVERSE.

APN 029-114-13

A description of the physical condition of the monument as found and as set or reset: _____
SET 3/4" I.P. & TAG PLS 5296 AS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on APRIL 27, 2001.

Signed [Signature] L.S. or R.C.E. Number PLS 5296

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 19, 2001 and examined
and filed SEPTEMBER 21, 2001.

Signed [Signature] Title DEPUTY
PLS NO. 7128

County Surveyor's Comment _____

