
CORNER RECORD Docum		nt Number <i>APN. 038-432-02</i>	
City of		MARIN	
Brief Legal Description 107 48 , RING MC	OUNTAIN SUB.	TIBURON - 20 R.	M.48
CORNER Government Corner	TYPE Control □	COORDINATES ((Optional)
☐ ☐ Meander ☐	Property 🗵	N	7 🗆 NAD83 🗆
Rancho □ Date of Survey 6/2		Elev	
Corner – Left as found X Found and tagged	☐ Established 🛚	Reestablished 🛭	Rebuilt 🛘
Identification and type of corner found: Evidence used to ide	•		
FOUND SUBDIVISON STREET MONUME INDICATED HEREON. PERFORME			
ESTABLISHED CORNERS AND LIN			
A description of the physical condition of the monument as			
FOUND MONUMENTS AND NORTH INDICATED.	CORNER OF LO,	T 48 UNDISTURB	ED AS
mercer (ce.			
SURVEYOR'S STATEMENT		GED LA	ND SUR
This Corner Record was prepared by me or under my di	rection in conformance	with Steph	
the Land Surveyor's Act on		- - - - - - - -	(C) (D)
Signed P.L.S or R.C.E.	No. <i>PL56234</i>	LIC. NO	1/31/06 ★
COUNTY SURVEYOR'S STATEME	ENT	Office Control	
This Corner Record was received <u>JULY 2, 200</u>	3		CALIFOR
and examined and filed JULY 10, 2003			
Signed P.L.S or R.C.E.	No. 7128		TACKO
Title COUNTY SURVEYOR		SCA CRA	KOR
County Surveyor's Comment		S Exp). <u>12/31/06</u> X No. 7128 X
		The state of the s	OF CALIFOR



SURVEY PLAT LANDS OF PETRINI 338 BLACKFIELD DR., TIBURON APN. 038-432-02

MARIN COUNTY, CA.

JN.103-20



BOB WALLING TECHNICAL SERVICES

P.O. Box 1346 • Glen Ellen, CA 95442 (707) 938-1593

(415)382-1593 UNE 2003