


CORNER RECORD

Document Number A.P. # 46-010-26City of MILL VALLEYCounty of MARIN, CaliforniaBrief Legal Description LOT 6, MOUNT TAMALPAIS ESTATES SUBD. 20 MAPS 97

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


CORNER INTERSECTION OF COURSES S89°06'56"E
53.78 & N05°32'28"E 150.00, LOT 6, 20 MAPS 97.
CORNER REESTABLISHED FROM ORIGINAL CONTROL
POINTS.

N. EDGEWOOD AVE., MILL VALLEYA description of the physical condition of the monument as found and as set or reset: SET 5/8" REBAR WITH ALUMINUM CAP STAMPED L.S.2771. OLD MONUMENT LYING NEARBY.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on DEC 22 19 92

Signed Paul B. Neese L.S. or R.C.E. Number L.S. 2771



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-4 19 93 and examined

and filed 1-4 19 93

Signed [Signature] Title _____



County Surveyor's Comment _____