


# CORNER RECORD

Document Number 46-091-03City of MILL VALLEYCounty of MARIN, CaliforniaBrief Legal Description PARCEL TWO/ 1 PM 34

## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☒  
Rancho ☐ Other ☐  
Date of Survey 6/16/99

## COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
REESTABLISH THE ANGLE POINT ON THE SOUTHERLY LINE OF MARIN VIEW AVENUE  
BETWEEN THE TWO COURSES SOUTH 63° 23' EAST, 154.55 FEET & SOUTH 52° 20' EAST  
158.04 FEET AS SHOWN UPON PARCEL TWO OF 1 PM 34. ESTABLISHED FROM FOUND  
IRON PIPES OF RECORD ALONG THE WESTERLY LINE OF PARCEL TWO AT THE  
NORTHWEST AND SOUTHWEST CORNER OF SAID PARCEL. SEE SKETCH ON REVERSE SIDE.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
SET ONE HALF INCH REBAR WITH PLS CAP 5379 AFFIXED TO TOP AND DRIVEN  
FLUSH WITH EXISTING GROUND GRADE.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyors' Act on JUNE 30TH 19 99.

Signed Douglas J. Scranton L.S. or R.C.E. Number PLS 5379  
RENEWAL 6/30/00



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 9 19 99 and examined  
and filed JULY 12 19 99.

Signed John M. Wooley Title DEPUTY



County Surveyor's Comment \_\_\_\_\_