


CORNER RECORD

Document Number _____

City of VICINITY OF MILL VALLEY County of MARIN, CaliforniaBrief Legal Description LOT 4 PER 19 R.M. 90**CORNER TYPE**

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey 11-4-94

**COORDINATES
(Optional)**

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE OVER


A description of the physical condition of the monument as found and as set or reset: _____

SEE OVER

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on FEBRUARY 3 19 95

Signed David Contreras L.S. or R.C.E. Number 5065

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received FEBRUARY 6 19 95 and examined and filed 2-7 19 95.

Signed Robert Darrell Beaumont Title DES



County Surveyor's Comment _____