


CORNER RECORD

Agency Index CR24-061Document Number 052-490-08(ADJ)City of UNINCORPORATED County of MARIN, CaliforniaBrief Legal Description FND 6" DIA CONC AT CL INT OF DRAKE AVE & DONAHUE ST (RM21-042)**CORNER TYPE****COORDINATES (Optional)**

- ☐ Government Corner ☐ Control
☐ Meander ☒ Property
☐ Rancho ☐ Other

Date of Survey February 15, 2024

N. _____ E. _____

Elevation _____

Units ☐ Metric ☒ U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902PLS Act Ref.: ☐ 8765(d) ☒ 8771 ☐ 8773 ☐ Other:

Corner/
Monument: ☐ Left as found ☐ Established ☐ Rebuilt ☒ Pre-Construction
☐ Found and tagged ☐ Reestablished ☒ Referenced ☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:


☐ See sheet #2 for description(s):

FOUND 6-INCH DIAMETER CONCRETE, BROKEN, IN MONUMENT WELL AT CENTERLINE INTERSECTION OF DRAKE AVENUE & DONAHUE STREET, AS SHOWN ON THAT RECORD MAP ENTITLED 'MAP OF MARIN CITY U.S.A.' FILED IN BOOK 21 AT PAGE 42, MARIN COUNTY RECORDS. SET FOUR 1/2-INCH IRON PIPES WITH YELLOW PLASTIC PLUGS STAMPED PLS 8614 AS REFERENCE POINTS TO PRESERVE THE CENTER OF THE FOUND CONCRETE MONUMENT PRIOR TO WATERLINE CONSTRUCTION.

SURVEYOR'S STATEMENT



This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on January 30, 2025.Signed Anthony G. Cinquini (P.L.S.) or R.C.E. No. 8614**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received January 30, 2025and examined and filed February 03, 2025.Signed T.W. Park P.L.S. 8176Title County Surveyor**County Surveyor's Comment**

**LEGEND**

- ROADWAY CENTERLINE
 ——— ADJACENT PROPERTY LINE
 - - - SURVEY TIE


- FOUND 6" DIAMETER
CONCRETE, BROKEN, IN
MONUMENT WELL,
REFERENCED CENTER
- SET 1/2" IRON PIPE WITH
YELLOW PLASTIC PLUG
TAGGED PLS 8614

**NOTES**

ALL DISTANCES AND DIMENSIONS ARE IN US
SURVEY FEET AND DECIMALS THEREOF.

ALL TIES ARE AT RIGHT ANGLES UNLESS
OTHERWISE NOTED.

ALL LINES ARE STRAIGHT-LINE TIES UNLESS
OTHERWISE NOTED.



CINQUINI & PASSARINO, INC.
LAND SURVEYING

- ▲ BOUNDARY
 ▲ TOPOGRAPHIC
 ▲ CONSTRUCTION
 ▲ SUBDIVISIONS

1360 No. Dutton Ave.
 Santa Rosa, Ca. 95401
 Phone: (707) 542-6268
 Fax: (707) 542-2106

WWW.CINQUINIPASSARINO.COM