CORNER RECORD				Document Number <u>APN - 070 - 133 - 13</u>			
	NBRAE				MARIN		
Brief Legal Description	COMMON LINE	LOT.	3 713	4714	, 7 RM 6	4	
	COR	NER TY	PE		COORDINAT	ΓES (Optio	onal)
	Government Corner		Control		N E Zone	NAD27 II A	NAD83 II
	Meander Rancho		Property Other		NAD83 Epoch		————
	Date of Survey						NVD88 □ perial □
Corner - Left	as found	gged [⊒ Estat	olished 🎾	Reestablished	□ Re	built 🗆
Identification and type of	corner found: Evidence used	to ident	ify or proce	edure use	d to establish or ree	stablish the	corner:
	L MONUMENTS						
	MONUMENTS F						
	A CUMBRE AL		CLOSE	ily u	THE A	IONUME	ethe
SHOWN ON	REYERSE.						
							·
A description of the phys	ical condition of the monumer	nt as fou	nd and as	set or res	et: SET PK	4 TAG	. IN
	R AT COMMON						
AND 713; 51	ET 3/4" 1.P. 4 T	AG,	PLS 5	296,	AT COMMO	N EAS	STERLY
	SAID LOTS.	· · · · · · · · ·					
	OUDVEWODIO OTATELAN					ONA	LLAND
	SURVEYOR'S STATEME						H. J. O. S.
This Corner Record was	s prepared by me or under n	ny direct	tion in con	formance	with		L.S. SIN
the Land Surveyor's Act	AUGUST 3	0,		2005	·		296 ~
Signed	P.L.S or R	.C.E. No	PLS	5296	<u>.</u>	12	-51-05
						100	CALIF
" (COUNTY SURVEYOR'S STA	TEMENT	-				
This Corner Record was	received SEPTEMB	ER 19	7,2009	5		(49)	TACK TACK
and examined and filed	OCTOBER 12,	2005	<u> </u>				, Model E
Signed	P.L.S or R	.C.ENo	7128	8			(12-21-n/x
Title COUNTY S	SRUEYOR					O. T.	No. 7128
						11	OF CAREER PARTY
County Surveyor's Con	nment						
AL	· · · · · · · · · · · · · · · · · · ·						
· · · · · · · · · · · · · · · · · · ·							

