


CORNER RECORD

Document Number APN 100-261-02

City of UNINCORPORATED DILLON BEACH County of MARIN, California

Brief Legal Description LOT 2 OLEANA MARIN 13 MAPS 37



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey 12-10-99

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SET LOT 2 CORNERS AT RECORD POSITION FROM FOUND
MONUMENTS, PER 13 MAPS 37.

A description of the physical condition of the monument as found and as set or reset:


⊙ - FOUND BRASS DISK IN MONUMENT WELL
 ● - FOUND 3/4" IRON PIPE TAGGED RCE 7595
 ○ - SET 3/4" IRON PIPE TAGGED LS 4483
 R - RECORD DATA M - MEASURED C - CALCULATED

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 2/15/99

Signed FRED M. PHELPS No. 4483 R.L.S. or R.C.E. No. LS 4483



SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 20, 1999

and examined and filed DECEMBER 21, 1999

Signed John M. Wooley R.L.S. or R.C.E. No. 26450

Title DEPUTY

County Surveyor's Comment _____



