


CORNER RECORD

Document Number A.P. #100-291-03

City of UNINCORPORATED

County of MARIN, California

Brief Legal Description LOT 104 OCEANA MARIN - UNIT 4



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey 6-17-94

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset: _____

⊙ = FOUND BRASS DISC IN MONUMENT WELL

● = FOUND 3/4" IRON PIPE TAGGED RCE

○ = SET 3/4" IRON PIPE TAGGED LS 4483

R = RECORD DATA PER OCEANA MARIN - UNIT 4 / 14 MAPS 65

M = MEASURED / C = CALCULATED

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 7-26-94 19__.

Signed FRED M. PHELPS L.S. or R.C.E. Number LS 4483



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-28- 1994 and examined

and filed 7-29 1994.

Signed RDB Title DES

County Surveyor's Comment _____



