


CORNER RECORDDocument Number I.N. 1994-66882City of Vicinity NovatoCounty of Marin, CaliforniaBrief Legal Description Meander Line over Parcel 3 per 14-MAPS-15; Marin County Records.**CORNER TYPE**

Government Corner ☐ Control ☐
 Meander ☒ Property ☐
 Rancho ☐ Other ☐
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner – Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☒

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found original 2" x 2" redwood hub with brass escutcheon with concrete collar per 14-MAPS-15.

A description of the physical condition of the monument as found and as set or reset: _____

Set 3/4" I.D. iron pipe with plastic plug "DANSKIN PLS 4794", as shown upon reverse side. Set pipe, set at sub-grade, is 0.76' below original hub, due to road repairs.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 28 November 2006

Signed [Signature] P.L.S or R.C.E. No. PLS 4794

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 4, 2006

and examined and filed JANUARY 4, 2007

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

