


CORNER RECORD

Documented Number AP # 143-350-22

City of Novato

County of Marin, California

Brief Legal Description Parcel B. 12 - PM - 30



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐

COORDINATES(Optional)

N. _____
E. _____

Zone _____ NAD27 ☐ NAD83 ☐

NAD83 Epoch _____

Elevation _____

Date of Survey 2/17/2015

Vert. Datum: NGVD 29 ☐ NADV88 ☐

Meas. Units: Metric ☐ Imperial ☐

Corner- Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Iron Pipes as shown on Parcel Map, 12 - PM - 30

A description of the physical condition of the monument as found and as set or reset: _____

Set 3/4" iron pipes with plastic cap "LS 5814"

Shown on attached diagram.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 4/22/16

Signed William E. Schroeder

P.L.S. or R.C.E. No.: PLS 5814

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 12, 2015 and examined

and filed APRIL 27, 2016

Signed R. G. Simonitch

P.L.S. or R.C.E. No.: 7821

Title _____

County Surveyor's Comment _____

