


CORNER RECORD

Document Number 143.421.39
 City of Novato County of MARIN California

Brief Legal Description LOT 8A 15 OS 81



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☐
 Rancho ☐ Other ☐
 Date of Survey 8/23/2007

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISH THE WESTERLY LINE OF LOT 8A
15 OS 81 FROM FOUND ORIGINAL CORNER
AT THE MOST NORTHWESTERLY CORNER OF SAID
LOT. REFER TO SKETCH ON REVERSE SIDE
FOR DETAILS.

A description of the physical condition of the monument as found and as set or reset:

Set 1/2" rebar/PLS 5379 AT RANDOM INTERVALS
ALONG SAID LINE (DRIVEN FLUSH TO SURROUNDING
GRADE) & SET BRASS PIN W/ BRASS TAG LS 5379 IN
CONCRETE BASE OF FENCE POST AT SOUTHWESTERLY CORNER

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 8/31 2007

Signed Douglas J. Scranton P.L.S. or R.C.E. No. PLS 5379

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 9-4-2007

and examined and filed 10-8-2007

Signed [Signature] P.L.S. or R.C.E. No. 30212

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



DO SCRANTON SURVEYING NOVATO, CA