CORNER RECORD

Agency Index DPW#21-061 Document Number APN 146-012-10 City of , California Novato Marin County of Parcel 2 of Parcel Map, 8 PM 1, Marin County Records Brief Legal Description **CORNER TYPE** COORDINATES (Optional) Government Corner Control Elevation Meander Property Units U.S. Survey Foot Metric Rancho Other Horizontal Datum **Epoch Date** Date of Survey April 16, 2021 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: X 8765(d) 8771 8773 Other: Left as found Pre-Construction Established Rebuilt Corner/ Monument: Found and tagged Reestablished Post-Construction Referenced Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): Found 6 monuments and reset 2. Held iron pipes in good condition marking easterly boundary; found northwest corner bent at 45 degrees with wood plug and tack, no tag, not held; found one wood hub on westerly line no tack or tag; found additional wood hub with tack and tag; found southwest corner with wood plug, tack & tag pushed down into pipe 0.1; set 5/8 rebar with yellow cap, PLS 7950 as shown. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on April 19, 2021 7950 Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed TRACY W Signed PARK NO. 8176 Title **County Surveyor's Comment**

Page 1 of 2

HighDefinitionSurveying

415-827-6370

1857 Rainier Circle, Petaluma, California, 94954

53.52 R1 S 89°48'00"

J:\21309-Caldwell\Dwg\21309CR.dwg