CORNER RECORD	Document	
City of Novato	County of	Marin, California
Brief Legal Description Parcel 2, 7 PM 28		
	perty 🔀	COORDINATES (Optional) N E NAD27
Corner- Left as found Found and tagged Esta	ablished 🔀	Reestablished Rebuilt
Identification and type of corner found: Evidence used to iden Found 3/4" Iron Pipes with Nail & Tag, LS 3049, at corn Found 3/4" Iron Pipe with Tag, RCE 17562, at SE corner A description of the physical condition of the monument as for Monumentation along Northern Property line of said	ers of Wester r of Parcel 2 a ound and as set	rly line of Parcel 2 as shown on 7 PM 28. as shown on 11 PM 56. t or reset: _ Set Hub and Tack survey
SURVEYOR'S STATEMENT This corner Record was prepared by me or under my direction in cotton the Land Surveyor's Act on October 15, 2008 Signed P.L.S. or R.C.E. No.	onformance with	No. 30465 No. 30465 No. 30465 No. 30465 OSAJ31/2010 EXPIRES OF CALIFORNIA
COUNTY SURVEYOR'S STATEMEN	NT	
This Corner Record was received OCTOBER 20, 2 and examined and filed NOVEMBER 19, 2008 Signed P.L.S. or R.C.E. No		Exp. 12-31-08 AND SUPERIOR TO THE COP CALLS OF C
County Surveyor's Comment		· · · · · · · · · · · · · · · · · · ·
·		

Borpels-1297

