


CORNER RECORD

COUNTY OF MARIN T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOVT. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



Not Applicable

CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Not Applicable.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

The NORTHEAST CORNER OF LOT 104 OF THE MAP OF KADEN PARK, UNIT 3, 13 RM 14; SET 3/4" IRON PIPE WITH LS TAG 5379

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐ Not Applicable
 STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

MAP OF KADEN PARK
 UNIT 3 (13 RM 14)



LOT 104 ~ 68 DRAKEWOOD LANE
 NAVAJO, CA

150-461-32

SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY WILLIAM J. SCHEIDT LICENSED LAND SURVEYOR UNDER NO. 5379
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT OF 1907
 ON SEPTEMBER 11 1989
 SIGNED: Douglas J. Scheidt
 L.S. or R.C.E. No.: LS 5379
 Exp. 6/30/1990
 SEAL

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED _____ 19____
 BY: Richard A. Carlson
 TITLE: Asst. Director / Dep. Surveyor

DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET YES ☐ NO ☒

03 SCRAUTION SUBVERTING 845 DRIVE AVE #208 NAVAJO, CA

NR # 99.53