## CORNER RECORD

Document Number AP#174-070-63 Fairfax County of Marin , California Lot 1, 19 RM 57 Brief Legal Description **CORNER TYPE COORDINATES (Optional)** E. Government Corner Control Elevation Metric U.S. Survey Foot X Meander Property Units Rancho Other Horizontal Datum Epoch Date Zone Date of Survey May 20, 2021 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: × 8765(d) 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): All Property Corners of Lot 1, 19 RM 57 (said "to be set" with 3/4" Iron Pipe RCE 12247) were searched for and not found except for the shown NE'ly Property Corner. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with May 21, 2021 the Professional Land Surveyors' Act on 30465 P.L.S. or R.C.E. No. Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed P.L.S. or R.E.E. No. 9292 Signed Title **County Surveyor's Comment** 

21-084

Agency Index

