	CORNER RECORD Document Number 174 · 083 · 10
	City of FAIR-FAX County of MARIN , Californ
•	Brief Legal Description LOT 197, MAP OF OAK MANOR, Unit 3, 9 RM 44
æ	Corner – Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☑ Rebuilt ☐
D) SCKANTON SUKVEYING NOVXTO, CA	Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: KEESTABLISH A PORTICH OF THE NORTHERLY LINE OF Let 197, MAP OF OAK MANCK Unit 3, 9 RM 44 & ALSO THE RIGHT OF WAY UNE ON VEN COURT & A PORTICH OF THE SCUTHERLY LINE OF SAID LOT 197 FROM EXISTING STANDARD STREET MONUMENTS PER SAID 9 RM 44 ON MARIELE DRIVE. A description of the physical condition of the monument as found and as set or reset: Refer to Sketch on Reverse Side for Octails; Set 1/2" redar With plastic cap affixed to 10 to 9 & STAMPED SCRANTON, PLS 5379 & OKIVEN Flush With SURROUNDING BRADE. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Stoveyor's act on VERNOARY 13 2007 Signed PLS of R.C.E. No. PLS 5379 COUNTY SURVEYOR'S STATEMENT This Corner Record was received FEBRUARY 15, 2007 and examined and filed MARCH 26, 2007 Signed PLS of R.C.E. No. PLS of R.C.E. No. PLS of R.C.E. No. PLS of R.C.E. No. REPS. 123-03 # Report 123 PR. No. 7128 # Rep. 123-03 # Report 123 PR. No. 7128 # Rep. 123-03 # R
$\tilde{\mathcal{Q}}$	Title COUNTY SURVEYOR
1	County Surveyor's Comment
)	

Borpels-1297 JN 10702

