



JERRICO ASSOCIATES
SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903


A.P. # 174-083-23

6619

CORNER RECORD

1/4

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
CORNER TYPE: GOVT. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐
CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Standard street monuments found as shown.


Lot 189 Oak Manor Unit Three (9 R.M. 44) Fairfax Ave, Ca.

PHYSICAL DESCRIPTION OF MONUMENTS, REBUILT OR PERPETUATED

Set re-bar and cap L.S. 3887



CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON June 12 1986

SIGNED: _____
L.S. or R.C.E. No.: _____



COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED June 23 1986
AND EXAMINED AND FILED June 23 1986
BY: Charles E. Murphy
TITLE: County Surveyor

STATEMENT ON BACK OF SHEET

YES ☐ NO ☒



JERRICO ASSOCIATES
 SUITE 27
 77 MARK DRIVE
 SAN RAFAEL, CA 94903

174-083-23

6619

CORNER RECORD

2/4

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Standard street monuments found as shown.


Lot 189 Oak Manor Unit Three (9 R.M. 44) Fairfax, Ca.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set re-bar and cap L.S. 3887



CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
 STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON June 12 1986 BRUNNER, JR.


SIGNED [Signature]
 L.S. or R.C.E. No. 3887



My Certificate Expires
June 30, 1989

COUNTY Marin SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED June 23 1986
 AND EXAMINED AND FILED June 23 1986
 BY: [Signature]
 TITLE: County Surveyor

YES ☐ NO ☒



JERRICO ASSOCIATES

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903


174-083-23

6619

CORNER RECORD

3/4

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐
CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Standard street monuments found as shown.


Lot 189 Oak Manor Unit Three (9 R.M. 44) Fairfax, Ca.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set re-bar and cap L.S. 3887


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON June 23, 1986
SIGNED: [Signature]
L.S. or R.G.E. No. 3887

STATE OF CALIFORNIA
SEAL



COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED June 23, 1986
AND EXAMINED AND FILED June 23, 1986
BY: [Signature]
CIVIL TITLE: Deputy County Surveyor

STATEMENT ON BACK OF SHEET

YES ☐ NO ☒



JERRICO ASSOCIATES
SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903


174-083-23

6619

CORNER RECORD

4/4

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐
CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Standard street monuments found as shown.


Lot 189 Oak Manor Unit Three (9 R.M. 44) Fairfax , Ca.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set re-bar and cap L.S. 3887



CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON June 12 19 86

SIGNED: E. J. Sumner
L.S. or R.C.E. No. 3887



COUNTY SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS RECEIVED June 23 19 86
AND EXAMINED AND FILED June 23 19 86
BY: Charles E. Murphy
TITLE: Deputy County Surveyor

My Certificate Expires
June 30, 1989

STATEMENT ON BACK OF SHEET

YES ☐ NO ☒