

CORNER RECORD

Document Number 114-170-03
County of MARIN, California

City of FAIRFAX County of MARIN, California
Brief Legal Description LOT 6 The CAPPE SUBV. Unit 2 20 MAPS 38

CORNER TYPE

Government Corner ☐ Control ☐

Meander ☐ Property ☒

Rancho ☐ Other ☐

Date of Survey July 8th & 10th 2002

COORDINATES (Optional)

N. _____
E. _____

Zone _____ NAD27 ☐ NAD83 ☐

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 ☐ NAVD88 ☐

Meas. Units: Metric ☒ Imperial ☐

Corner – Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISH MISC. CORNERS FOR LOT 6, THE CAPPE
SUBV. UNIT # 2. (20 MAPS 38) FROM EXISTING STREET
MONUMENTS OF RECORD ON MAJOR VIEW DRIVE.
REFER TO SKETCH ON REVERSE SIDE FOR LOT CORNERS
REESTABLISHED PER THIS SURVEY.

A description of the physical condition of the monument as found and as set or reset:

Unless noted otherwise, set 1/2" rebar with
PLS CAP 5379 AFFIXED TO TOP & DRIVEN FLUSH
WITH SURROUNDING GRADE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on July 11th 2002

Signed Wagner J. [Signature] P.L.S or R.C.E. No. PLS 5379
Renewal 6.30.04

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received JULY 15, 2002

and examined and filed JULY 24, 2002

Signed Chukwudi Nwankwo PLS or R.C.E. No. 26450

Title DEPUTY

County Surveyor's Comment _____ 7



JN 10235

