
## **CORNER RECORD**

7	Documented Number	174-190-03	
City of Fairfax	County of Marin		, California
Brief Legal Description Lot 6. The Cappe Subdivision, 20 Maps 38			
CORNER TY Government Corner	PE Control	COORDINATE N.	ES(Optional)
Meander Rancho	Property X Other	Zone NAI NAD83 Epoch Elevation	027 NAD83
Date of Survey_ 12/11/2	2012	Vert. Datum: NGVD Meas, Units: Metric	29 NADV88
Corner- Left as found Found	and tagged Establish	ned Reestablished	X Rebuilt
per this office as shown upon the Marin C Refer to sketch on reverse side for details.  A description of the physical condition of the mon Set one half inch rebar with yellow plastic The plastic cap is stamped "Scranton PLS	nument as found and as set or r	eset:	
SURVEYOR'S  This Corner Record was prepared by me or under my	S STATEMENT y direction in conformance with		SED LAND SUPPLIED IN SUPPLIED
Signed COUNTY SURVEY	P.L.S. of R.C.E. No.:	PLS 5379	No. 5379 Renswal 6-30-2014 OF CALIFOR
This Corner Record was received $\frac{12-20}{30}$ and filed $\frac{1-30-2013}{30}$		and examined	RICHARD G. SIMONITCH
Signed Publication	P.L.S. o <del>r R.C.E.</del> No.:	7821	MONTON SIMONITCH SO SIMONITCH S
Title DEPUTY COUNTY S	URVEYOR		COFCALIFO





## LEGEND

- O SET 1/2" REBAR WITH PLASTIC CAP STAMPED
  "LS 5379 SCRANTON" ATTACHED TO TOP OF REBAR
- R1 MARIN COUNTY CORNER RECORD FILED JULY 24, 2002 FOR APN 174-190-03 DONE BY THIS OFFICE

ALL DIMENSIONS GIVEN IN FEET AND DECIMALS THEREOF

NO EASEMENTS ARE SHOWN

BASIS OF BEARINGS SAME AS SHOWN UPON R 1