


CORNER RECORDDocument Number 97-41816City of Vicinity of San AnselmoCounty of Marin

, California

Brief Legal Description Lot 409, Map of Sleepy Hollow Unit Four, 6-Maps-79**CORNER TYPE**

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey _____

**COORDINATES
(Optional)**

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
 Set 3/4" I.D. galvanized iron pipes with plastic plug "PLS 4794" at Northwest corner, Northeast corner and at
 angle point in Northerly line, S 56° 21' E 73.55' from Northwest corner of Lot 409, Map of Sleepy Hollow
 Unit Four, recorded in Book 6 of Maps, at Page 79, Marin County Records. Set 1 1/2" x 1 1/2" hub with bronze
 nail & tag "LS 4794" S 15° 06' 50" E 78.6' from Northwest corner, and set 1" x 2" with bronze nail & tag "LS 4794"
 S 86° 34' W 117.8' and S 86° 34' W 224.0' from Northeast corner of said Lot 409.


A description of the physical condition of the monument as found and as set or reset: _____

As shown upon reverse side

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on 30 January 19 98.

Signed [Signature] L.S. or R.C.E. Number PLS 4794

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received FEBRUARY 4 19 98 and examined
 and filed FEBRUARY 6 19 98.

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____

Phillip A. Danskin & Associates
Land Surveyor
Sonoma, CA
Survey No. 461

Set 1 1/2" x 1 1/2" redwood hub
with bronze nail & tag "LS 4794"

Set 3/4" I.D. galvanized iron pipes
with plastic plugs "PLS 4794"

Set 1" x 2" stake with bronze
nail & tag "LS 4794"

