


CORNER RECORD

Document Number _____

City of SAN ANSELMO County of MARIN, California

Brief Legal Description LOT 4, PARCEL MAP LANDS OF BRADBURY (18 PM44)



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey APRIL 1998

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND PIPES, SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SET 3/4" IRON PIPES WITH PLASTIC CAPS, RCE 30465;
SET NAILS WITH BRASS TAGS, RCE 30465; SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on APRIL 9 1998.

Signed Jay P. H. L.S. or R.C.E. Number RCE 30465



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received APRIL 15 1998 and examined

and filed APRIL 16 1998.

Signed John M. Wooley Title DEPUTY



County Surveyor's Comment _____



LEGEND

- FOUND HUB PER 18 PM 44
- FOUND 1/2" IRON PIPE PER 18 PM 44
- ⊗ FOUND 3/4" IRON PIPE PER 18 PM 44
- SET 3/4" IRON PIPE & CAP, RCE 30465
- ✱ SET NAIL & TAG, RCE 30465



SCALE: 1" = 100'