


CORNER RECORD

Document Number _____

City of San AnselmoCounty of Marin, CaliforniaBrief Legal Description Being Lot 1001, Map of Sleepy Hollow Unit Ten (12RM4B)**CORNER TYPE**

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey Nov. 10, 2006

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner -- Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Standard Street Monuments per 12RM4B,
See Page 2.

A description of the physical condition of the monument as found and as set or reset: Set 3/4" Iron
Pipes with plastic cap "LS 5814", see Page 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on 1/26/07

Signed William E. Schroeder P.L.S. or R.C.E. No. 5814

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-29-2007

and examined and filed FEBRUARY 1, 2007

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

