

CORNER RECORD

COUNTY OF _____ T. _____ R. _____ MERIDIAN _____ CALIFORNIA
CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☒
CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



A.P. # 179-092-07 & 08

CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☒ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found R.R. spike monuments on surface of Corrillo Drive. Held for bearing. Held Southwesterly monument for control to re-establish lot corner.




PHYSICAL DESCRIPTION OF MONUMENTS, REBUILT OR PERPETUATED

Replaced front lot corner (Lots 118/119, San Rafael Meadows Unit Two -- 7 RM 20) with 3/4" iron pipe, tag R. E. 17486.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

ALL STREET CONTROL FITS CURB LINES WITHIN 0.1 FEET



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON Sept 12 1985
SIGNED: J. A. McQuinn
R.C.E. No. 17486

REGISTERED PROFESSIONAL ENGINEER
CHARLES E. MURPHY
COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED Sept. 17 1985
AND EXAMINED AND FILED Sept. 18 1985
No. 18,657
BY: Charles E. Murphy
TITLE: Deputy County Surveyor
DOCUMENT No. _____
STATE OF CALIFORNIA
SEAL
STATEMENT ON BACK OF SHEET
YES ☐ NO ☒