




JERRICO ASSOCIATES

7578

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903Document Number 179-202-10**CORNER RECORD**City of San RafaelCounty of Marin, CaliforniaBrief Legal Description Lot 4 Los Ranchitos Estates 18 MAPS 29**CORNER TYPE**Government Corner ☐ Control ☐Meander ☐ Property ☒Rancho ☐ Other ☐Date of Survey June 7, 2006**COORDINATES (Optional)**

N. _____

E. _____

Zone _____ NAD27 ☐ NAD83 ☐

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 ☐ NAVD88 ☐Meas. Units: Metric ☐ Imperial ☐Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found standard monuments on Ranch Road.

A description of the physical condition of the monument as found and as set or reset: _____

ABFound iron pipe and illegible tag.**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on June 7, 2006Signed J.E. BrunnerP.L.S. or R.C.E. No. LS 3887**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received JUNE 14, 2006and examined and filed JULY 18, 2006Signed [Signature]P.L.S. or R.C.E. No. 7128Title COUNTY SURVEYOR

County Surveyor's Comment _____

FD. STD.
MON.

LOS RANCHITOS ESTATES 18 MAPS 29

LOT 2

LOT 3

179-202-09

Set hub &
inverted tag.

LOT 4

179-202-10

(B) FD. IRON PIPE &
ILLEGIBLE TAG

209.00

94.441

N 65° 27' 03" W

DEBES RANCH ROAD

70' private
roadway easement
for the benefit
of Lots 1 thru
5. Per 18RM 29


SURVEY OF LINE
BETWEEN LOT 3 & LOT 4
LOS RANCHITOS ESTATES
SAN RAFAEL, CALIFORNIA.

JUNE 2006

JERRICO ASSOCIATES 77 MARK DR., SAN RAFAEL, CA.

S-7578

(A) FD. IRON PIPE &
ILLEGIBLE TAG



N 58° 59' 56" E

194.944

57.497

46.92

45.39

70' P.U.E. & S.S.E

N 21° 58' 01" W 234.965

20'

120.00

RANCH ROAD

N 27° 23' 40" E 319.439

20'

FD. STD.
MON.