

CORNER RECORD



JERRICO ASSOCIATES

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903


7327

City of San Rafael

Document Number 179-331-02

County of Marin, California

Brief Legal Description Lot 2 Portola Estates Unit One 11 RM 18



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey Sept 30, 1998

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Standard subdivision monuments on Portola.


A description of the physical condition of the monument as found and as set or reset: _____

(A) (B) Set #5 rebar and cap LS 3887.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on Sept 30 19 98.

Signed [Signature] L.S. or R.C.E. Number LS 3887




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 2 19 98 and examined
and filed October 6 19 98.

Signed [Signature] Title Deputy



County Surveyor's Comment _____



SURVEY W'LY LINE
 AP 179-331-02
 SAN RAFAEL CALIFORNIA.

SEPT. 1998

JERRICO ASSOC. 77 MARK DRIVE SAN RAFAEL CA.

S-7327