


CORNER RECORD

City of Vicinity of San Rafael

Document Number 180-042-28

County of MARIN, California

Brief Legal Description Sheet 7 of 8 // 15 O.S. 36



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒
Date of Survey 2-1-06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☒

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Iron Pipe on Birch Way, and the Railroad Spike at
Intersection of Birch Way and Adrian Way were destroyed
during sewer construction.

see back

A description of the physical condition of the monument as found and as set or reset:

Replaced Iron Pipe and railroad spike in positions
shown on 15 O.S. 36, with
Standard County Monument
see back

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Feb 15 2006

Signed Michael A. Brogan P.L.S or R.C.E. No. LS 5767



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received February 21, 2006

and examined and filed March 21, 2006

Signed _____ P.L.S or R.C.E. No. 7128

Title County Surveyor

County Surveyor's Comment _____



15 O.S. 36

Sheet 7 of 8

DISTURBED I.P. REPLACED
WITH STANDARD COUNTY MONUMENT

} opposite

APN 180-042-28

INDOLA

AFARAFEL WAY

DESTROYED R.R. SPIKE
REPLACED WITH
STANDARD COUNTY MONUMENT

FOUND I.P.
NO TACK

FOUND R.R. SPIKE

ADRIAN

WAY

BIRCH WAY

GALLINAS VILLAGE
UNIT ONE
7 MAPS 12

GALLINAS VILLAGE
UNIT ONE
7 MAPS 12

MAP OF
VENETIA
S 75

NORTH SAN PEDRO ROAD
LANDS

COUNTY

THE

OF
1570
O.R.
296

1640 O.R. 202

PARCEL 1

PARCEL 2

1872 O.R. 590

FOUND HUB

