




JERRICO ASSOCIATES

7422

CORNER RECORDSUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903Document Number 180-291-10City of San RafaelCounty of Marin, CaliforniaBrief Legal Description Pol. (2) 20 Parcel Maps 16**CORNER TYPE**

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey March 22, 2001

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as shown in 20 PM 16 as well as
points re-set by others (see other side).


A description of the physical condition of the monument as found and as set or reset: _____

See plat on the other side of this page.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on March 22, 2001

Signed [Signature] P.L.S. or R.C.E. No. LS 3887

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received MAY 9, 2001
 and examined and filed MAY 11, 2000

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment _____

