CORNER RECORD		Document N	umberA	.P.# 200-172-93
City of	.	County of	MARIN	, California
Prief Legal Description 27 O.S. 75				
CORNER TYPE		C	OORDINATES (Opt	ional)
Government Corner Meander	☐ Contro		E. Zone NAD83 Epoch	NAD27 NAD83 D
Rancho	Other 5/29/03		Vert. Datum: Meas. Units:	NGVD29 NAVD88 C Metric Imperial C
Corner- Left as found ☐ Found and tagged	☐ Establish	ed Reest	ablished Rel	built 🗍
dentification and type of corner found: Evid ESTABLISHED THE PROPERTY CORNE				
A description of the physical condition of the	monument a	s found and a	s set or reset:	SEE SHEET 2.
SURVEYOR'S STATE	MENT		······································	
his Corner Record was prepared by me or u	ınder my direc	tion in confor	mance with	ED LAND SI
the Land Surveyor's Act on MAY 28		2003		JENCE P. O.P.
Signed Caurones PDoyle P.L.S	S. or R.C.E. No	. <u>P.L.S.</u>	4694	No. 4694 ★ No. 4694 ★ Exp. 9/30/03 ★
COUNTY SURVEYOR'S ST	TATEMENT			FIE OF CALL FORM
his Corner Record was receivedJUK	JE 2,20	2003		CALI
nd examined and filed JUNE 5,	2003			SEC TACKER
Signed P.L.S	s. or R.C.E. No	. 7128		91 85 12/21 PA
title COUNTY SURVEYOR				No. 7128
County Surveyor's Comment				TOAL

