Agency Index Z1-1Z4 **CORNER RECORD** Document Number AP#200-262-03 Marin Mill Valley County of . California Lot 61, 14 RM 66 Brief Legal Description **CORNER TYPE COORDINATES (Optional)** E.____ Government Corner Control Elevation U.S. Survey Foot X Units Meander Property Metric Rancho Other Horizontal Datum Zone Epoch Date Date of Survey October 16, 2021 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: × 8765(d) 8771 8773 Other: Established Left as found Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): The two Monuments found/shown at the rear property corners of Lot 61 were 3" Iron Pipes with Brass Caps labeled "Bureau of Land Management" of Unknown Origin. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with No. October 30, 2021 the Professional Land Surveyors' Act on 30465 P.L.S. or R.C.E. No. <u>30465</u> Signed **COUNTY SURVEYOR'S STATEMENT** 11.2.21 This Corner Record was received and examined and filed P.L.S. or R.C.E. No. 9292 Signed Title County Surveyor's Comment-

