CORNER RECORD	)		Docume	nt NumberA.I	P.# 200-281-15
City ofMILL VALLE	Y	-	County of	MARIN	, California
rief Legal Description	LOT 129 14 R	.M. 79			
	CORNER TYPE	COORD	NATES (Options	N	
	Government Corner	Control		Zone NAD83 Epo	·
	Meander Rancho Date of Survey 0	☐ Property ☐ Other 1/19/04		Elev. Vert. Datum: Meas. Units:	NGVD29 □ NAVD88 □ Metric □ Imperial □
Corner- Left as found	Found and tagged	Established		ablished 🔲 Rebu	ilt 🔲
Identification and type of co	rner found: Evidence us OPERTY LINE FROM				
A description of the physical	condition of the monum	ent as found and as	set or reset:	SEE SHEET	2.
SURVE	YOR'S STATEMENT pared by me or under my	direction in conform	nance with		SED LAND SUP
the Land Surveyor's Act on	P.D. P.	L.S. or R.C.E. No.	2004 P.L.S.	4694	No. 4694 Exp. 9/30/05 ★
COUNTY SU	RVEYOR'S STATEMENT ived FEBR	UAR 4,20	04		OF CALL FORMER
and examined and filed	FEBRUAR	1 10,200	)4		SO LAND SU
igned Signed Signed Survival S	( )	.S. or <del>R.C.E.</del> No	7128		Exp. 12(3)/06 *
County Surveyor's Comment					POFCALFOR
<u>)                                    </u>					
		<del></del> -	<del></del>		

