


CORNER RECORD

Agency Index

Document Number

Post Const
DPW # 19-150
APN 006-031-17 ADJ

City of SAN ANSELMO County of MARIN, California
Brief Legal Description STANDARD STREET MONUMENT REPLACING RAILROAD SPIKE IN ASPHALT PAVEMENT
PER CORNER RECORD (APN 006-031-17)



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey 09/12/2019

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units Metric ☐ U.S. Survey Foot ☐

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902PLS Act Ref.: ☒ 8765(d) ☐ 8771 ☐ 8773 ☐ Other: _____

Corner/
Monument: ☐ Left as Found ☐ Established ☒ Rebuilt ☐ Pre-Construction
☐ Found and Tagged ☐ Reestablished ☐ Referenced ☒ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☒ See sheet #2 for description(s):

USING FOUND MONUMENT REFERENCE POINTS PER CORNER RECORD (APN 006-031-17), INSTALLED A STANDARD
STREET MONUMENT IN CAN, 3" DISK PUNCHED AND STAMPED (LS 7893), REPLACING ORIGINAL RAILROAD SPIKE.
WORK WAS DONE AFTER THE COMPLETION OF THE SAN FRANCISCO BLVD PAVEMENT PROJECT (SEE PAGE 2 OF 2).

Surveyor's Comment

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on NOVEMBER 4, 20 19.

Signed [Signature] P.L.S. or R.C.E. No. LS 7893

County Surveyor's Comment

This Corner Record was received DECEMBER 30, 2019
and examined and filed JAN. 30, 2020.

Signed [Signature] P.L.S. OR R.C.E. NO. 9292Title DEPUTY C.S.

County Surveyor's Comment _____