

CORNER RECORD



JERRICO ASSOCIATES

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903


7156

Document Number 6-118-05,21

City of San Anselmo

County of Marin, California

Brief Legal Description Lots 8,9,10,11,12 Block 28 Amended map of Sequoia
Park Section 2 4 RM 21



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey August 17, 1995

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☒ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
(A) (B) Found 3/4" IP & LS 2535


A description of the physical condition of the monument as found and as set or reset: _____

(C) (D) (E) (F) Set #5 rebar and cap LS 3887
(G) Set nail and tag LS 3887 in concrete.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on August 21 19 95


Signed [Signature] L.S. or R.C.E. Number LS 3887



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 27 19 95 and examined
and filed 10-27 19 95

Signed [Signature] Title DCS



County Surveyor's Comment _____

